

57HS Series Hybrid Stepping Motors



General Specifications

Step Angle Degree	1.8°				
Step Angle Accuracy	±5%(full step, no load)				
Temperature Rise	80°CMax				
Ambient Temperature	-10°C +50°C				
Insulation Resistance	100MΩmin.500VDC				
Dielectric Strength	500VAC for one minute				
Shaft Radial Play	0.06 Max.(450g-load)				
Shaft Axial Play	0.08 max.(450g-load)				

Electrical Specifications

Model Number	Connection	Motor Length L inch (mm)	Holding Torque Oz-in (Nm)	Number of Leads	Phase Current (Amps)	Phase Resistance (Ohm)	Phase Inductance (mH)	Rotor Inertia Oz-in-sec² (g.cm²)	Detent Torque Oz-in (g.cm)	Weight Oz (kg)
57HS04	(Bipolar) Series	1.61 (41)	56.64 (0.4)	6	2.0	1.4±10%	1.4±20%	0.001917 (135)	-	15.87 (0.45)
	Unipolar		39.65 (0.28)	6	2.8	0.7±10%	0.35±20%			
57HS09	(Bipolar) Parallel	2.13 (54)	184.08 (1.3)		4.0	0.4±10%	1.2±20%	0.003692 (260)	5.664 (408)	21.16 (0.6)
	(Bipolar) Series		184.08 (1.3)	8	2.0	1.6±10%	4.8±20%			
	Unipolar		127.44 (0.9)		2.8	0.8±10%	1.2±20%			
57HS13	(Bipolar) Parallel	2.99 (76)	254.88 (1.8)	254.88 (1.8) 8 2.0 2.0±10	4.0	0.5±10%	2.1±20%	0.006532 (460)	9.912 (714)	35.27 (1.0)
	(Bipolar) Series		254.88 (1.8)		2.0	2.0±10%	8.4±20%			
	Unipolar		184.08 (1.3)		1.0±10%	2.1±20%				
57HS22	(Bipolar) Parallel	3.19 (81)	311.52 (2.2) 5.7 0.4±10% 1.8±20%							
	(Bipolar) Series		311.52 (2.2)	8	2.8	1.6±10%	7.2±20%	0.006816 (480)	-	40.57 (1.15)
	Unipolar		212.4 (1.5)		4.0	0.8±10%	1.8±20%			

^{*} Above motors are our typical models, and if you need a customization motor, please contact us.

Mechanical Specifications (Unit=mm, 1 inch=25.4mm)




Figure 1: Mechanical specification of 57HS04




Figure 2: Mechanical specification of 57HS09




Figure 3: Mechanical specification of 57HS13






Figure 4: Mechanical specification of 57HS22


Wiring Diagrams



(a) 57HS04 unipolar connection



(b) 57HS04 bipolar (series) connection



A+ BLU

Acom RED

YEL

Stepping
Driver

B+ BRN

Bcom

B
BLK


ORG WHT

(e) 57HSxx unipolar connection (8 leads)

Figure 5: Wiring diagrams

Speed-Torque Characteristics

Unipolar and bipolar half coil, because we're using less turns, doesn't give us great low speed torque, but because of the low inductance, holds the torque out to high speeds. Bipolar series uses the full coil so it gives very good low speed torque. But because of the high inductance, the torque drops off rapidly. Bipolar parallel also uses the full coil so it gives good low speed performance. And its low inductance allows the torque to be held out to high speeds. But remember, we must increase current by 40% to get those advantages. Speed-torque curves show the maximum torques that can be output at a given speed. When selecting a motor, make sure the required torque falls within the particular curve.






Figure 8: Speed-torque curves of the 57HS13

1200 1400

• 57HS22




Figure 9: Speed-torque curves of the 57HS22

Remarks:

200 400

0.2

1. Title "57HS09 Rated current/phase: Parallel, 4.2A (RMS); Series, 2.1A (RMS); Half-coil, 2.8A (RMS)" means "When the 57HS09 used in parallel mode, its current/phase is 4.2A (RMS); When the 57HS09 used in series mode, its current/phase is 2.1A (RMS); When the 57HS09 used in half-coil or unipolar mode, its current/phase is 2.8A (RMS)".

2000 2200 2400

- 2. Legend "57HS09, Parallel, H860B, 36VDC, 6.0A (Peak), Half Step" means "This speed-torque curve of the 57HS09 (connected in parallel mode) was done with the H860B driver. The settings of the H860B are 6.0A (Peak), Half Step and use 36VDC power supply ".
- 3. The actual characteristics will vary depending on the driver used. Please use these curves only for reference purposes when selecting a motor. You must also conduct a thorough evaluation with the actual driver to be used. Please consult "Leadshine Motor and Driver Packages" for more information about this issue.